




Model # 78620

SUBARU BALL JOINT PULLER



**FOR DIFFICULT TO REMOVE,
SEIZED, RUSTED AND/OR CORRODED
BOLT-IN SUBARU BALL JOINTS**



SALES AND MARKETING
1230 Santa Anita Avenue, Suite E
South El Monte, CA 91733
Phone: (800) 221-9705
USA Toll Free
Fax: (877) 318-2194
Phone: (626) 228-3170
Fax: (626) 228-3124

372 Old US Highway
52 South
Mount Airy, NC 27030

Model	Applications
78620	Subaru Baja 2003+, Forester 1998+, Impreza 1993+, Legacy 1990+, Outback 2000+ and more

**DESIGNED FOR EASY USE WITH VEHICLE
ON JACK STANDS USING A DEEP 24MM
SOCKET AND IMPACT OR HAND WRENCH**

**OR USE INCLUDED 5/8-18 THREAD
ADAPTER WITH ANY COMMON SLIDE
HAMMER**

**Astro Pneumatic
Tool Company**

E-mail : astrotools@astrotools.com
WEBSITE : www.astrotools.com



UNDERCAR KIT

