



**Astro Pneumatic
Tool Company**

372 Old US Highway 52 South
Mount Airy, NC 27030

Model:


7409

Product Type:

**9pc. 3/8" DRIVE TWIST SOCKET
DAMAGED FASTENER REMOVAL SET**

PARTS BREAKDOWN

Call 1.800.221.9705 for questions concerning performance of the product or other inquiries.



Parts List

<i>Index No.</i>	<i>Part No.</i>	<i>Description</i>	<i>Qty</i>
1	7409-01	10mm 3/8" Drive Twist Socket	1
2	7409-02	11mm 3/8" Drive Twist Socket	1
3	7409-03	12mm 3/8" Drive Twist Socket	1
4	7409-04	13mm 3/8" Drive Twist Socket	1
5	7409-05	14mm 3/8" Drive Twist Socket	1
6	7409-06	15mm 3/8" Drive Twist Socket	1
7	7409-07	16mm 3/8" Drive Twist Socket	1
8	7409-08	17mm 3/8" Drive Twist Socket	1
9	7409-09	19mm 3/8" Drive Twist Socket	1
10	7409-10	75mm Knock-up Bar	1
11	7409-CASE	Case Only	1